

**Flood Control Project Maintenance
Levee Inspections**

2018 Channel Summary Report

Overall Unit and Item Ratings

San Joaquin County Flood Control and Water Conservation District

Duck Creek Diversion Channel

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

North Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
M *	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	M *

* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

South Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
M *	Vegetation & Obstructions	M *
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

South Littlejohn Creek North Branch

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**Unit Cover Sheet****2018 Channel Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Channel
Duck Creek Diversion Channel

Channel Rating	A
Date of Inspection	6/28/2018
DWR Inspector	Dave Torres
Accompanied By	Jim Caruso SJCF&WCD

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	06/28/2018 06/28/2018	Dave Torres

Check Point / View

Diversion Structure / Down

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_31			

Action/Comments

Inspector Comments: Minimal vegetation in the channel should not impede the flow.

Photo 1 of 2 : CH_2018_NA0017_43_31_20180702_00013.jpg



View of the vegetation in the diversion channel looking downstream during 2018 inspection.

Rating **	A	Issue No.	31 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_31			

Photo 2 of 2 : CH_2018_NA0017_43_31_20180530_00011.jpg



View of the vegetation in the diversion channel looking downstream during 2017 inspection.

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_43_c_2012_1			

Action/Comments

Inspector Comments: No sedimentation was present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	06/28/2018 06/28/2018	Dave Torres

Check Point / View

Diversion Structure / Down (cont)

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_43_c_2012_32			

Action/Comments

Inspector Comments: No erosion or bank caving is present in the channel.

No Photos

Rating **	N	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c_2012_33			

Action/Comments

Inspector Comments: No revetment is present at this location.

No Photos

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		37.938270 °
Category	Rivers, Channels & Designated Flood			-120.990130 °
Item	Encroachments			
DWR ID	DWR_NA0017_43_c_2012_34			

Action/Comments

Inspector Comments: No trash or debris observed in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	06/28/2018 06/28/2018	Dave Torres

Check Point / View

Farmington Rd/ Hwy 4 / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_11			

Action/Comments

Inspector Comments: The Minimal vegetation in the channel doesn't appear to obstruct the flow of the channel.

Photo 1 of 1 : CH_2018_NA0017_43_11_20180702_00014.jpg



View of the vegetation in the channel looking upstream, 2018.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_43_c_2012_12			

Action/Comments

Inspector Comments: No sedimentation was present at this location.

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_43_c_2012_13			

Action/Comments

Inspector Comments: No erosion or bank caving was present during inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	06/28/2018 06/28/2018	Dave Torres

Check Point / View

Farmington Rd/ Hwy 4 / Up (cont)

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c_2012_14			

Action/Comments

Inspector Comments: Existing riprap appears to be properly maintained.

Photo 1 of 2 : CH_2018_NA0017_43_14_20180702_00015.jpg



View of the revetments on the right bank of the channel looking upstream, 2018

Rating **	A	Issue No.	14 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c_2012_14			

Photo 2 of 2 : CH_2018_NA0017_43_14_20180702_00017.jpg



View of the revetments on the left bank of the channel looking upstream, 2018.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Encroachments			
DWR ID	DWR_NA0017_43_c_2012_2			

Action/Comments

Inspector Comments: No trash or debris was found during inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	06/28/2018 06/28/2018	Dave Torres

Check Point / View

Farmington Rd/ Hwy 4 / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_16			

Action/Comments

Inspector Comments: Minimal vegetation is present in the channel but it doesn't appear to obstruct the flow of the channel.

Photo 1 of 1 : CH_2018_NA0017_43_16_20180702_00018.jpg



View of the vegetation looking downstream of the channel. Summer 2018

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_43_c_2012_17			

Action/Comments

Inspector Comments: No sedimentation was present at this location.

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_43_c_2012_18			

Action/Comments

Inspector Comments: No bank caving or erosion was found in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	06/28/2018 06/28/2018	Dave Torres

Check Point / View

Farmington Rd/ Hwy 4 / Down (cont)

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		37.929807 °
Category	Rivers, Channels & Designated Flood			-120.991183 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c_2012_19			

Action/Comments

Inspector Comments: Existing riprap appears to be properly maintained.

Photo 1 of 2 : CH_2018_NA0017_43_19_20180702_00020.jpg



View of the revetments on the right bank of the channel looking downstream, 2018.

Rating **	A	Issue No.	19 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.929807 °
Category	Rivers, Channels & Designated Flood			-120.991183 °
Item	Revetments			
DWR ID	DWR_NA0017_43_c_2012_19			

Photo 2 of 2 : CH_2018_NA0017_43_19_20180702_00019.jpg



View of the revetments on the left bank of the channel looking downstream, 2018.

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		37.930250 °
Category	Rivers, Channels & Designated Flood			-120.991220 °
Item	Encroachments			
DWR ID	DWR_NA0017_43_c_2012_20			

Action/Comments

Inspector Comments: No trash or debris are obstructing the flow of the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	06/28/2018 06/28/2018	Dave Torres

Check Point / View

Confluence with South Littlejohn Creek / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_43_c_2012_21			
Action/Comments				
Inspector Comments: Vegetation growth in the channel does not appear to impede the flow.				

Photo 1 of 1 : CH_2018_NA0017_43_21_20180702_00021.jpg



View of the confluence during 2018 inspection.

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_43_c_2012_22			
Action/Comments				
Inspector Comments: No sedimentation was present at this location.				

No Photos

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Encroachments			
DWR ID	DWR_NA0017_43_c_2012_25			
Action/Comments				
Inspector Comments: No trash or debris are obstructing the flow of the channel.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
Duck Creek Diversion Channel	0.90	06/28/2018 06/28/2018	Dave Torres

Check Point / View

Confluence with South Littlejohn Creek / Down

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		37.925730 °
Category	Rivers, Channels & Designated Flood			-120.992290 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_43_c_2012_23			

Action/Comments

Inspector Comments: Minimal erosion was present during inspection but does not appear to impact the capacity of the channel.

Photo 1 of 1 : CH_2018_NA0017_43_23_20180702_00022.jpg



Minimal erosion on left bank of channel at confluence, 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2018 Channel Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Channel
North Littlejohn Creek

Channel Rating	M *
Date of Inspection	6/22/2018 - 6/28/2018
DWR Inspector	Dave Torres
Accompanied By	Jim Caruso SJCFC&WCD

* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Upstream Limit / Up

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_6			

Action/Comments

Inspector Comments: Minimal vegetation was found, but they do not obstruct the flow of the channel.

Photo 1 of 2 : CH_2018_NA0017_42_6_20180702_00077.jpg



View of the vegetation on the upstream of the channel, 2018.

Rating **	A	Issue No.	6 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_6			

Photo 2 of 2 : CH_2018_NA0017_42_6_20180530_00001.jpg



View of the vegetation on the upstream of the channel.

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_7			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Upstream Limit / Up (cont)

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_8			

Action/Comments

Inspector Comments: No erosion is present at this location during inspection.

No Photos

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_9			

Action/Comments

Inspector Comments: No revetments are found at this location.

No Photos

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		37.919430 °
Category	Rivers, Channels & Designated Flood			-121.034800 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_10			

Action/Comments

Inspector Comments: No trash, debris, or obstruction is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Hewit Lane / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		37.920600 °
Category	Rivers, Channels & Designated Flood			-121.037920 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_11			

Action/Comments

Inspector Comments: Minimal vegetation exist, but it will not impede the flow of the channel.

Photo 1 of 2 : CH_2018_NA0017_42_11_20180702_00073.jpg



View of the channel looking upstream during 2018 inspection.

Photo 2 of 2 : CH_2018_NA0017_42_11_20180530_00002.jpg



View of the channel looking upstream during 2017 inspection.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_12			

Action/Comments

Inspector Comments: No sedimentation is present on the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Hewit Lane / Up (cont)

Rating **	N	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_14			

Action/Comments

Inspector Comments: Revetments are not present at this location.

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_15			

Action/Comments

Inspector Comments: No trash or debris are present in the channel.

No Photos

Rating **	A	Issue No.	112	GPS Lat/Long
Issue Type +	Ma	Location *		37.920600 °
Category	Rivers, Channels & Designated Flood			-121.037920 °
Item	Concrete Surfaces			
DWR ID	DWR_NA0017_42_c_2012_112			

Action/Comments

Inspector Comments: The concrete surface appeared to be in good condition with no negligible spalling, scalling or cracking.

Photo 1 of 1 : CH_2018_NA0017_42_112_20180530_00048.jpg



View of the culvert on the upstream of the channel. Summer 2017

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Hewit Lane / Up (cont)

Rating **	A	Issue No.	113	GPS Lat/Long
Issue Type +	Ma	Location *		37.920600 °
Category	Rivers, Channels & Designated Flood			-121.037920 °
Item	Gates			
DWR ID	DWR_NA0017_42_c_2012_113			

Action/Comments

Inspector Comments: Slide gates appeared to be in good operational condition.

Photo 1 of 2 : CH_2018_NA0017_42_113_20180702_00075.jpg



View of the slide gates on the upstream of the channel, 2018.

Rating **	A	Issue No.	113 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.920600 °
Category	Rivers, Channels & Designated Flood			-121.037920 °
Item	Gates			
DWR ID	DWR_NA0017_42_c_2012_113			

Photo 2 of 2 : CH_2018_NA0017_42_113_20180530_00050.jpg



View of the slide gate on the upstream of the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Hewit Lane / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_16			
Action/Comments				
Inspector Comments: Walnut tree exists on left side of the shoulder. It does not obstruct the flow, but it could fall down in the creek.				

Photo 1 of 2 : CH_2018_NA0017_42_16_20180702_00074.jpg



View of the vegetation on the channel looking downstream during 2018 inspection.

Rating **	A	Issue No.	16 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_16			

Photo 2 of 2 : CH_2018_NA0017_42_16_20180530_00004.jpg



View of the vegetation on the channel looking downstream during 2017 inspection.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_17			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Hewit Lane / Down (cont)

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_18			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_19			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		37.920584 °
Category	Rivers, Channels & Designated Flood			-121.037914 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_20			
Action/Comments				
Inspector Comments: No trash or debris are present in the channel.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Van Allen Rd / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_21			

Action/Comments

Inspector Comments: Vegetation growth on the slopes need to be removed. Flow is likely not impeded.

Photo 1 of 2 : CH_2018_NA0017_42_21_20180702_00070.jpg



View of the vegetation on the channel looking upstream. Summer 2018

Photo 2 of 2 : CH_2018_NA0017_42_21_20180530_00006.jpg



View of the vegetation on the channel looking upstream. Summer 2017

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_22			

Action/Comments

Inspector Comments: No sedimentation was found during inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Van Allen Rd / Up (cont)

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_23			

Action/Comments

Inspector Comments: No erosion is present at this location during inspection.

No Photos

Rating **	N	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_24			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_25			

Action/Comments

Inspector Comments: No debris were present during inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Van Allen Rd / Down

Rating **	M	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_26			

Action/Comments

Inspector Comments: Various lengths of logs, and vegetation growth appeared to impede the flow of the channel.

Photo 1 of 2 : CH_2018_NA0017_42_26_20180702_00071.jpg



View of vegetation looking downstream of the channel. Summer 2018

Photo 2 of 2 : CH_2018_NA0017_42_26_20180530_00008.jpg



View of heavy vegetation looking downstream of the channel. Summer 2017

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_27			

Action/Comments

Inspector Comments: No sedimentation is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Van Allen Rd / Down (cont)

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_28			

Action/Comments

Inspector Comments: No erosion is present at this location during inspection.

No Photos

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_29			

Action/Comments

Inspector Comments: Existing revetments appear to be properly maintained.

Photo 1 of 1 : CH_2018_NA0017_42_29_20180702_00072.jpg



View of existing revetments on the right bank of the channel looking downstream, 2018.

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		37.918960 °
Category	Rivers, Channels & Designated Flood			-121.056260 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_30			

Action/Comments

Inspector Comments: No trash was found.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Jack Tone Rd / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_31			

Action/Comments

Inspector Comments: Minimal vegetation exists in the channel, however need to clear woody vegetation in channel.

Photo 1 of 2 : CH_2018_NA0017_42_31_20180702_00067.jpg



View of the channel looking upstream during 2018 inspection.

Photo 2 of 2 : CH_2018_NA0017_42_31_20180530_00011.jpg



View of the channel looking upstream during 2017 inspection.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_32			

Action/Comments

Inspector Comments: No shoaling or sedimentation present on the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Jack Tone Rd / Up (cont)

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_33			

Action/Comments

Inspector Comments: No erosion is present at this location during inspection.

No Photos

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_34			

Action/Comments

Inspector Comments: No revetments are present at this location.


No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_35			

Action/Comments

Inspector Comments: Minimal trash was present on the channel during inspection.

Photo 1 of 1 : CH_2018_NA0017_42_35_20180702_00068.jpg



View of the debris in the channel looking upstream during 2018 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Jack Tone Rd / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_36			
Action/Comments				
Inspector Comments: Minimal vegetation on the channel should not obstruct the flow.				

Photo 1 of 1 : CH_2018_NA0017_42_36_20180702_00069.jpg



View of the channel looking downstream, 2018.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_37			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_38			
Action/Comments				
Inspector Comments: No erosion is present at this location during inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Jack Tone Rd / Down (cont)

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_39			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		37.921460 °
Category	Rivers, Channels & Designated Flood			-121.147570 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_40			

Action/Comments

Inspector Comments: Minimal debris was present at this location.

No Photos

Check Point / View

Mariposa Rd / Up

Rating **	A	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_41			

Action/Comments

Inspector Comments: Minimal vegetation on the channel should not impede the flow.

Photo 1 of 2 : CH_2018_NA0017_42_41_20180625_00065.jpg



View of upstream of the channel during 2018 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Mariposa Rd / Up (cont)

Rating **	A	Issue No.	41 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_41			
Action/Comments				
Inspector Comments: Minimal vegetation on the channel should not impede the flow.				

Photo 2 of 2 : CH_2018_NA0017_42_41_20180530_00014.jpg



View of upstream of the channel during 2017 inspection.

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_42			
Action/Comments				
Inspector Comments: No sedimentaion is present.				

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_43			
Action/Comments				
Inspector Comments: No erosion observed at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Mariposa Rd / Up (cont)

Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_44			

Action/Comments

Inspector Comments: Existing revetments appear to be properly maintained.

No Photos

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_45			

Action/Comments

Inspector Comments: No trash or other obstructions are present in the channel.

No Photos

Check Point / View


Mariposa Rd / Down

Rating **	A	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_46			

Action/Comments

Inspector Comments: Minimal vegetation does not impede the flow on the channel.

Photo 1 of 2 : CH_2018_NA0017_42_46_20180625_00066.jpg



View of the downstream of the channel. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View


Mariposa Rd / Down (cont)

Rating **	A	Issue No.	46 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_46			

Action/Comments

Inspector Comments: Minimal vegetation does not impede the flow on the channel.

Photo 2 of 2 : CH_2018_NA0017_42_46_20180530_00016.jpg



View of the downstream of the channel. Summer 2017

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_47			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_48			

Action/Comments

Inspector Comments: No erosion observed at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Mariposa Rd / Down (cont)

Rating **	N	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_49			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		37.915879 °
Category	Rivers, Channels & Designated Flood			-121.189095 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_50			

Action/Comments

Inspector Comments: No trash was present at this location.

No Photos

Check Point / View

Highway 99 / Up

Rating **	A	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_51			

Action/Comments

Inspector Comments: Woody vegetation upstream from bridge should be removed to prevent impact to channel capacity.

Photo 1 of 2 : CH_2018_NA0017_42_51_20180625_00064.jpg



View of the upstream of the channel. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Highway 99 / Up (cont)

Rating **	A	Issue No.	51 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_51			
Action/Comments				
Inspector Comments: Woody vegetation upstream from bridge should be removed to prevent impact to channel capacity.				

Photo 2 of 2 : CH_2018_NA0017_42_51_20180530_00018.jpg



View of the upstream of the channel. Summer 2017

Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_52			
Action/Comments				
Inspector Comments: Sedimentation was present at this location.				

No Photos

Rating **	A	Issue No.	53	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_53			
Action/Comments				
Inspector Comments: No erosion was present during inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Highway 99 / Up (cont)

Rating **	N	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_54			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

Rating **	A	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_55			
Action/Comments				
Inspector Comments: No trash was present at this location.				

No Photos

Check Point / View

Highway 99 / Down

Rating **	A	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_56			
Action/Comments				
Inspector Comments: Minimal vegetation does not impede the flow on the channel.				

Photo 1 of 2 : CH_2018_NA0017_42_56_20180625_00063.jpg



View of the downstream end of the channel. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Highway 99 / Down (cont)

Rating **	A	Issue No.	56 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_56			
Action/Comments				
Inspector Comments: Minimal vegetation does not impede the flow on the channel.				

Photo 2 of 2 : CH_2018_NA0017_42_56_20180530_00021.jpg



View of the downstream end of the channel. Summer 2017

Rating **	A	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_57			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_58			
Action/Comments				
Inspector Comments: No erosion is present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Highway 99 / Down (cont)

Rating **	N	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_59			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

Rating **	A	Issue No.	60	GPS Lat/Long
Issue Type +	Ma	Location *		37.913239 °
Category	Rivers, Channels & Designated Flood			-121.225915 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_60			
Action/Comments				
Inspector Comments: Some trash was present during the inspection.				

No Photos

Check Point / View

Pock Lane / Up

Rating **	M	Issue No.	61	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_61			
Action/Comments				
Inspector Comments: Woody vegetation upstream may impede the flow of the channel.				

Photo 1 of 2 : CH_2018_NA0017_42_61_20180625_00061.jpg



View of the channel looking upstream during 2018 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Pock Lane / Up (cont)

Rating **	M	Issue No.	61 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_61			

Action/Comments

Inspector Comments: Woody vegetation upstream may impede the flow of the channel.

Photo 2 of 2 : CH_2018_NA0017_42_61_20180530_00025.jpg



View of the channel looking upstream during 2017 inspection.

Rating **	A	Issue No.	62	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_62			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	63	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_63			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Pock Lane / Up (cont)

Rating **	N	Issue No.	64	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_64			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	65	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_65			

Action/Comments

Inspector Comments: Minimal debris was present in the channel.

No Photos

Check Point / View

Pock Lane / Down

Rating **	A	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_66			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel.

Photo 1 of 2 : CH_2018_NA0017_42_66_20180625_00062.jpg



View of the channel looking downstream. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View


Pock Lane / Down (cont)

Rating **	A	Issue No.	66 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_66			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel.

Photo 2 of 2 : CH_2018_NA0017_42_66_20180530_00027.jpg



View of the channel looking downstream. Summer 2017

Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_67			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_68			

Action/Comments

Inspector Comments: No erosion or bank caving is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Pock Lane / Down (cont)

Rating **	N	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_69			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	70	GPS Lat/Long
Issue Type +	Ma	Location *		37.914290 °
Category	Rivers, Channels & Designated Flood			-121.238800 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_70			

Action/Comments

Inspector Comments: Some trash was present during the inspection.

No Photos

Check Point / View

South B Street / Up

Rating **	M	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_71			

Action/Comments

Inspector Comments: Moderate vegetation was present in the channel but flow would likely not be impeded.

Photo 1 of 2 : CH_2018_NA0017_42_71_20180625_00059.jpg



View of vegetation on the channel looking upstream. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

South B Street / Up (cont)

Rating **	M	Issue No.	71 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_71			

Action/Comments

Inspector Comments: Moderate vegetation was present in the channel but flow would likely not be impeded.

Photo 2 of 2 : CH_2018_NA0017_42_71_20180530_00030.jpg



View of vegetation on the channel looking upstream. Summer 2017

Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_72			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_73			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

South B Street / Up (cont)

Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_74			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_75			

Action/Comments

Inspector Comments: Some trash was present during the inspection.

No Photos

Check Point / View

South B Street / Down

Rating **	A	Issue No.	76	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_76			

Action/Comments

Inspector Comments: Minimal vegetation on the channel may not impede the flow.

Photo 1 of 2 : CH_2018_NA0017_42_76_20180625_00060.jpg



View of the vegetation looking downstream during 2018 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

South B Street / Down (cont)

Rating **	A	Issue No.	76 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_76			

Action/Comments

Inspector Comments: Minimal vegetation on the channel may not impede the flow.

Photo 2 of 2 : CH_2018_NA0017_42_76_20180530_00032.jpg



View of the vegetation looking downstream during 2017 inspection.

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_77			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

Rating **	A	Issue No.	78	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_78			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

South B Street / Down (cont)

Rating **	N	Issue No.	79	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_79			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	80	GPS Lat/Long
Issue Type +	Ma	Location *		37.913716 °
Category	Rivers, Channels & Designated Flood			-121.247761 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_80			

Action/Comments

Inspector Comments: Some trash was present during the inspection.

No Photos

Check Point / View

Airport Way / Up

Rating **	M	Issue No.	81	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_81			

Action/Comments

Inspector Comments: Moderate vegetation present in channel may impede the flow.

Photo 1 of 2 : CH_2018_NA0017_42_81_20180625_00057.jpg



View of the vegetation on the channel looking upstream. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Airport Way / Up (cont)

Rating **	M	Issue No.	81 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_81			
Action/Comments				
Inspector Comments: Moderate vegetation present in channel may impede the flow.				

Photo 2 of 2 : CH_2018_NA0017_42_81_20180530_00035.jpg



View of the vegetation on the channel looking upstream.

Rating **	A	Issue No.	82	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_82			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	83	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_83			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Airport Way / Up (cont)

Rating **	N	Issue No.	84	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_84			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

Rating **	U	Issue No.	85	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_85			
Action/Comments				
Inspector Comments: Individuals have erected a barrier from the overcrossing to the ground to provide shelter. Unable to determine how the tarp was anchored.				

Photo 1 of 1 : CH_2018_NA0017_42_85_20180702_00078.jpg



View of encroachment on upstream side of channel, 2018.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Airport Way / Down

Rating **	A	Issue No.	86	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_86			

Action/Comments

Inspector Comments: Moderate woody vegetation may impede the flow of the channel.


Photo 1 of 2 : CH_2018_NA0017_42_86_20180625_00058.jpg



View of the channel looking downstream. Summer 2018

Rating **	A	Issue No.	86 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_86			

Photo 2 of 2 : CH_2018_NA0017_42_86_20180530_00036.jpg



View of the channel looking downstream. Summer 2017

Rating **	A	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_87			

Action/Comments

Inspector Comments: No shoaling was found during the inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Airport Way / Down (cont)

Rating **	A	Issue No.	88	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_88			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

Rating **	N	Issue No.	89	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_89			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

Rating **	A	Issue No.	90	GPS Lat/Long
Issue Type +	Ma	Location *		37.912070 °
Category	Rivers, Channels & Designated Flood			-121.258811 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_90			
Action/Comments				
Inspector Comments: No trash or debris was present during the inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Producers Drive / Up

Rating **	A	Issue No.	91	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_91			

Action/Comments

Inspector Comments: Minimal vegetation may not impede the flow of the channel.

Rating **	A	Issue No.	91 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_91			

Photo 1 of 2 : CH_2018_NA0017_42_91_20180625_00055.jpg



View of the channel looking upstream during 2018 inspection.

Photo 2 of 2 : CH_2018_NA0017_42_91_20180530_00038.jpg



View of the channel looking upstream during 2017 inspection.

Rating **	A	Issue No.	92	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_92			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Producers Drive / Up (cont)

Rating **	A	Issue No.	93	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_93			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

Rating **	N	Issue No.	94	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_94			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	95	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_95			

Action/Comments

Inspector Comments: No trash was found during the inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Producers Drive / Down

Rating **	A	Issue No.	96	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_96			
Action/Comments				
Inspector Comments: Minimal vegetation was found, but the flow is not impeded.				

Photo 1 of 2 : CH_2018_NA0017_42_96_20180625_00056.jpg



View of the channel looking downstream. Summer 2018

Rating **	A	Issue No.	96 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_96			

Photo 2 of 2 : CH_2018_NA0017_42_96_20180530_00040.jpg



View of the channel looking downstream. Summer 2017

Rating **	A	Issue No.	97	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_97			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Producers Drive / Down (cont)

Rating **	A	Issue No.	98	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_98			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

Rating **	N	Issue No.	99	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_99			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	100	GPS Lat/Long
Issue Type +	Ma	Location *		37.908433 °
Category	Rivers, Channels & Designated Flood			-121.269214 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_100			

Action/Comments

Inspector Comments: No trash or debris is present in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

McKinley Avenue / Up

Rating **	M	Issue No.	101	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_101			
Action/Comments				
Inspector Comments: Vegetation, logs and other debris may impede the flow of the channel.				

Photo 1 of 3 : CH_2018_NA0017_42_101_20180625_00051.jpg



View of the heavy vegetation on the channel looking upstream during 2018 inspection.

Rating **	M	Issue No.	101 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_101			

Photo 2 of 3 : CH_2018_NA0017_42_101_20180530_00042.jpg



View of the heavy vegetation on the channel looking upstream. Summer 2017

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

McKinley Avenue / Up (cont)

Rating **	M	Issue No.	101 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_101			

Action/Comments

Inspector Comments: Vegetation, logs and other debris may impede the flow of the channel.

Photo 3 of 3 : CH_2018_NA0017_42_101_20180530_00043.jpg



View of the heavy vegetation on the channel looking upstream during 2016 inspection.

Rating **	M	Issue No.	102	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_102			

Action/Comments

Inspector Comments: Non aquatic grasses and sedimentation were present during the inspection.

Photo 1 of 1 : CH_2018_NA0017_42_102_20180530_00044.jpg



View of non-aquatic plants in the channel looking upstream.

Rating **	A	Issue No.	103	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_103			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

McKinley Avenue / Up (cont)

Rating **	N	Issue No.	104	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_104			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	M	Issue No.	105	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_105			

Action/Comments

Inspector Comments: Trash and debris are present in the channel.

Photo 1 of 1 : CH_2018_NA0017_42_105_20180625_00052.jpg



View of debris on the upstream end of the channel. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

McKinley Avenue / Down

Rating **	M	Issue No.	106	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2012_106			

Action/Comments

Inspector Comments: Vegetation and debris may impede the flow of the channel.

Photo 1 of 2 : CH_2018_NA0017_42_106_20180625_00053.jpg



View of the channel looking downstream during 2018 inspection.

Photo 2 of 2 : CH_2018_NA0017_42_106_20180530_00046.jpg



View of the channel looking downstream during 2017 inspection.

Rating **	A	Issue No.	107	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_42_c_2012_107			

Action/Comments

Inspector Comments: No sedimentation is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
North Littlejohn Creek	18.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

McKinley Avenue / Down (cont)

Rating **	A	Issue No.	108	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_42_c_2012_108			

Action/Comments

Inspector Comments: No erosion is present at this location.

No Photos

Rating **	N	Issue No.	109	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Revetments			
DWR ID	DWR_NA0017_42_c_2012_109			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	M	Issue No.	110	GPS Lat/Long
Issue Type +	Ma	Location *		37.907158 °
Category	Rivers, Channels & Designated Flood			-121.273935 °
Item	Encroachments			
DWR ID	DWR_NA0017_42_c_2012_110			

Action/Comments

Inspector Comments: Trash or debris are present in the channel.

Photo 1 of 1 : CH_2018_NA0017_42_110_20180625_00054.jpg



View of debris on the downstream end of the channel. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance
Unit Cover Sheet
2018 Channel Inspection Results

San Joaquin County Flood Control and Water Conservation District

Channel
South Littlejohn Creek

Channel Rating	M *
Date of Inspection	6/22/2018 - 6/28/2018
DWR Inspector	Dave Torres
Accompanied By	Jim Caruso SJCFC&WCD

* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Farmington Dam / Up

Rating **	A	Issue No.	119	GPS Lat/Long
Issue Type +	Ma	Location *		37.900580 °
Category	Rivers, Channels & Designated Flood			-120.936018 °
Item	Gates			
DWR ID	DWR_NA0017_44_c_2014_119			
Action/Comments				
Inspector Comments: The gate appears to be functional.				

Photo 1 of 1 : CH_2018_NA0017_44_119_20180703_00089.jpg



View of the release gate from Farmington Dam looking upstream of the creek. Summer 2018

Check Point / View

Farmington Dam / Down

Rating **	M	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		37.914340 °
Category	Rivers, Channels & Designated Flood			-120.937860 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_6			
Action/Comments				
Inspector Comments: Vegetation in the channel may impede the flow.				

Photo 1 of 1 : CH_2018_NA0017_44_6_20180703_00090.jpg



View of the vegetation on the channel. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Farmington Dam / Down (cont)

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914 °
Category	Rivers, Channels & Designated Flood			-120.934604 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_7			

Action/Comments

Inspector Comments: No sedimentation is present in the channel.

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914 °
Category	Rivers, Channels & Designated Flood			-120.934604 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_8			

Action/Comments

Inspector Comments: No erosion was found during the inspection.

No Photos

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		37.900914 °
Category	Rivers, Channels & Designated Flood			-120.934604 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_9			

Action/Comments

Inspector Comments: Existing riprap appeared to be maintained.

Photo 1 of 1 : CH_2018_NA0017_44_9_20180703_00091.jpg



View of the existing revetments looking downstream during 2018 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View				
Farmington Dam / Down (cont)				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		37.914340 °
Category	Rivers, Channels & Designated Flood			-120.937860 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_10			
Action/Comments				
Inspector Comments: No debris is present in the channel.				

No Photos

Check Point / View				
Wedding Chappel Crossing / Up				
Rating **	A	Issue No.	99	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_42_c_2013_99			
Action/Comments				
Inspector Comments: Minimal vegetation not likely to impede the flow in the gate downstream.				

Photo 1 of 1 : CH_2018_NA0017_44_99_20180703_00086.jpg



View of the vegetation on the channel looking upstream. Summer 2018

Rating **	A	Issue No.	100	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2013_100			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Wedding Chappel Crossing / Up (cont)

Rating **	A	Issue No.	101	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2013_101			

Action/Comments

Inspector Comments: No erosion was found during the inspection.

No Photos

Rating **	N	Issue No.	112	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2013_112			

Action/Comments

Inspector Comments: No revetments exist at this location.

No Photos

Rating **	A	Issue No.	103	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2013_103			

Action/Comments

Inspector Comments: No debris was found during inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Wedding Chappel Crossing / Up (cont)

Rating **	A	Issue No.	108	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Gates			
DWR ID	DWR_NA0017_44_c_2013_108			

Action/Comments

Inspector Comments: The pipe appeared to be in good condition.

Photo 1 of 1 : CH_2018_NA0017_44_108_20180703_00087.jpg



View of the pipe looking upstream of the channel. Summer 2018

Check Point / View

Wedding Chappel Crossing / Down

Rating **	U	Issue No.	104	GPS Lat/Long
Issue Type +	Ma	Location *		37.900332 °
Category	Rivers, Channels & Designated Flood			-120.939298 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2013_104			

Action/Comments

Inspector Comments: Heavy vegetation growth will impede the flow and may block approximately 50% capacity of the channel.

Photo 1 of 1 : CH_2018_NA0017_44_104_20180703_00088.jpg



View of the vegetation on the downstream of the channel during 2018 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Wedding Chappel Crossing / Down (cont)

Rating **	A	Issue No.	105	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2013_105			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	106	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2013_106			
Action/Comments				
Inspector Comments: No erosion was found during the inspection.				

No Photos

Rating **	A	Issue No.	107	GPS Lat/Long
Issue Type +	Ma	Location *		37.900040 °
Category	Rivers, Channels & Designated Flood			-120.938949 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2013_107			
Action/Comments				
Inspector Comments: No trash or debris present during the inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Henry Road / Up

Rating **	M	Issue No.	141	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2015_141			
Action/Comments				
Inspector Comments: Vegetation and logs were present that may impede the flow of the channel.				

Photo 1 of 2 : CH_2018_NA0017_44_141_20180703_00084.jpg



Wood trunks and vegetation may impede the flow of the channel.
Summer 2018

Rating **	M	Issue No.	141 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2015_141			

Photo 2 of 2 : CH_2018_NA0017_44_141_20180530_00057.jpg



Wood trunks and vegetation may impede the flow of the channel.
Summer 2017

Rating **	A	Issue No.	142	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2015_142			
Action/Comments				
Inspector Comments: No sedimentation was present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Henry Road / Up (cont)

Rating **	A	Issue No.	143	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2015_143			
Action/Comments				
Inspector Comments: No erosion was found.				

No Photos

Rating **	A	Issue No.	144	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161°
Category	Rivers, Channels & Designated Flood			-120.945289°
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2015_144			
Action/Comments				
Inspector Comments: No debris was found during inspection.				

No Photos

Rating **	A	Issue No.	150	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Gates			
DWR ID	DWR_NA0017_44_c_2015_150			
Action/Comments				
Inspector Comments: The pipe appears to be free of debris and does not appear to impede the flow of the channel.				

Photo 1 of 1 : CH_2018_NA0017_44_150_20180530_00061.jpg



View of the pipe looking upstream from the channel during 2017 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Henry Road / Down

Rating **	M	Issue No.	146	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2015_146			
Action/Comments				
Inspector Comments: Vegetation growth may impede the flow of the channel.				

Photo 1 of 1 : CH_2018_NA0017_44_146_20180703_00085.jpg



View of the vegetation on the downstream of the channel. Summer 2018

Rating **	A	Issue No.	147	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2015_147			
Action/Comments				
Inspector Comments: No shoaling or sedimentation was present.				

No Photos

Rating **	A	Issue No.	148	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2015_148			
Action/Comments				
Inspector Comments: No erosion was present during inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Henry Road / Down (cont)

Rating **	A	Issue No.	149	GPS Lat/Long
Issue Type +	Ma	Location *		37.903161 °
Category	Rivers, Channels & Designated Flood			-120.945289 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2015_149			

Action/Comments

Inspector Comments: No debris was found during inspection.

No Photos

Check Point / View

Escalon Bellota Rd / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_21			

Action/Comments

Inspector Comments: Minimal vegetation but not likely to impede the flow of the channel.

Photo 1 of 1 : CH_2018_NA0017_44_21_20180703_00092.jpg



View of the channel looking upstream during 2018 inspection.

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_22			

Action/Comments

Inspector Comments: No sedimentation is present in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Escalon Bellota Rd / Up (cont)

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_23			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_24			

Action/Comments

Inspector Comments: Existing riprap is properly maintained.

Photo 1 of 1 : CH_2018_NA0017_44_24_20180703_00093.jpg



Existing revetments left bank. Summer 2018

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_25			

Action/Comments

Inspector Comments: No trash or debris is present in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District


Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Escalon Bellota Rd / Down

Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_26			
Action/Comments				
Inspector Comments: Minimal vegetation was found in the channel not likely to impede the flow.				

Photo 1 of 1 : CH_2018_NA0017_44_26_20180703_00094.jpg



View of the channel looking downstream during 2018 inspection.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_27			
Action/Comments				
Inspector Comments: No sedimentation is present in this channel.				

No Photos

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_28			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Escalon Bellota Rd / Down (cont)

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_29			
Action/Comments				
Inspector Comments: Existing riprap is properly maintained.				

Photo 1 of 1 : CH_2018_NA0017_44_29_20180703_00095.jpg



View of the revetments on the left bank of the channel looking downstream during 2018 inspection.

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		37.925330 °
Category	Rivers, Channels & Designated Flood			-121.000120 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_30			
Action/Comments				
Inspector Comments: No trash or debris are present in the channel.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Stanley Rd / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_31			

Action/Comments

Inspector Comments: Minimal vegetation that will not impede flow.

Photo 1 of 1 : CH_2018_NA0017_44_31_20180703_00096.jpg



View of the channel looking upstream during 2018 inspection.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_32			

Action/Comments

Inspector Comments: No sediment was present in this channel.

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_33			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Stanley Rd / Up (cont)

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_34			

Action/Comments

Inspector Comments: Existing revetments were maintained properly on the channel bank. LMA has placed additional riprap under the bridge.

Photo 1 of 1 : CH_2018_NA0017_44_34_20180703_00097.jpg



View of the existing revetments on the right channel bank looking upstream. Summer 2018

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_35			

Action/Comments

Inspector Comments: No trash or debris was found during the inspection.

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Stanley Rd / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_36			
Action/Comments				
Inspector Comments: Minimal vegetation that will not impede flow.				

Photo 1 of 2 : CH_2018_NA0017_44_36_20180703_00098.jpg



View of the downstream of the channel. Summer 2018

Rating **	A	Issue No.	36 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_36			

Photo 2 of 2 : CH_2018_NA0017_44_36_20180530_00016.jpg



View of the downstream of the channel. Summer 2017

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_37			
Action/Comments				
Inspector Comments: No sediment was present in this channel.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View				
Stanley Rd / Down (cont)				
Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060°
Category	Rivers, Channels & Designated Flood			-121.027790°
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_38			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location.				

No Photos

Rating **	A	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_39			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained.				

Photo 1 of 2 : CH_2018_NA0017_44_39_20180703_00099.jpg



View of the revetments on the right bank of the channel. Summer 2018

Rating **	A	Issue No.	39 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_39			

Photo 2 of 2 : CH_2018_NA0017_44_39_20180530_00018.jpg



View of the revetments on the right bank of the channel.

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Stanley Rd / Down (cont)

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		37.920060 °
Category	Rivers, Channels & Designated Flood			-121.027790 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_40			

Action/Comments

Inspector Comments: No trash or debris is present at this location.

No Photos

Check Point / View

Van Allen Rd / Up

Rating **	A	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_41			

Action/Comments

Inspector Comments: Minimal vegetation that will not impede flow.

Photo 1 of 1 : CH_2018_NA0017_44_41_20180703_00080.jpg



View of the channel looking upstream. Summer 2018

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_42			

Action/Comments

Inspector Comments: No sediment was present in this channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Van Allen Rd / Up (cont)

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_43			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_44			

Action/Comments

Inspector Comments: LMA has placed new revetments on the banks of the channel. Permit #19000. Existing revetments are properly maintained.

Photo 1 of 1 : CH_2018_NA0017_44_44_20180703_00081.jpg



View of the revetment on the right bank of the channel looking upstream.
Summer 2018

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_45			

Action/Comments

Inspector Comments: No trash or debris was found during the inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Van Allen Rd / Down

Rating **	A	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_46			

Action/Comments

Inspector Comments: The vegetation growth around the channel is not impeding the flow.

Photo 1 of 1 : CH_2018_NA0017_44_46_20180703_00082.jpg



View of the channel looking downstream. Summer 2018

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_47			

Action/Comments

Inspector Comments: No sediment was present during inspection.

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_48			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Van Allen Rd / Down (cont)

Rating **	A	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_49			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained. LMA has placed more revetments on both banks of the channel. Permit #19000

Photo 1 of 1 : CH_2018_NA0017_44_49_20180703_00083.jpg



View of the existing revetment looking downstream. Summer 2018

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		37.913060 °
Category	Rivers, Channels & Designated Flood			-121.056230 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_50			

Action/Comments

Inspector Comments: No trash or debris is present at this location.

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Mariposa Rd / Up

Rating **	A	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_51			

Action/Comments

Inspector Comments: Minimal vegetation was present on the channel, but it may not impede the flow of the channel.

Photo 1 of 1 : CH_2018_NA0017_44_51_20180703_00076.jpg



View of the upstream of the channel. Summer 2018

Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_52			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	53	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_53			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Mariposa Rd / Up (cont)

Rating **	A	Issue No.	151	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2016_151			

Action/Comments

Inspector Comments: Existing revetments are properly maintained.

Photo 1 of 1 : CH_2018_NA0017_44_151_20180703_00077.jpg



View of the revetments on the upstream of the channel. Summer 2018

Rating **	A	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_55			

Action/Comments

Inspector Comments: No trash or debris is present at this location.

No Photos

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Mariposa Rd / Down

Rating **	A	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_56			
Action/Comments				
Inspector Comments: Minimal vegetation was present on the channel, but it may not impede the flow of the channel.				

Photo 1 of 1 : CH_2018_NA0017_44_56_20180703_00078.jpg



View of the channel looking downstream. Summer 2018

Rating **	A	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_57			
Action/Comments				
Inspector Comments: No sedimentation is present in the channel.				

No Photos

Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_58			
Action/Comments				
Inspector Comments: No erosion was found during the inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Mariposa Rd / Down (cont)

Rating **	M	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_59			
Action/Comments				
Inspector Comments: Existing revetments have vegetation that requires maintenance.				

Photo 1 of 2 : CH_2018_NA0017_44_59_20180703_00079.jpg



View of existing revetments on the channel banks looking downstream.
Summer 2018

Rating **	M	Issue No.	59 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_59			

Photo 2 of 2 : CH_2018_NA0017_44_59_20180530_00031.jpg



View of existing revetments on the channel banks looking downstream.

Rating **	A	Issue No.	60	GPS Lat/Long
Issue Type +	Ma	Location *		37.895050 °
Category	Rivers, Channels & Designated Flood			-121.118200 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_60			
Action/Comments				
Inspector Comments: No trash or debris was found during the inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Jack Tone Rd / Up

Rating **	A	Issue No.	61	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_61			

Action/Comments

Inspector Comments: Minimal vegetation was present in the channel but flow may not be impeded..

Photo 1 of 1 : CH_2018_NA0017_44_61_20180703_00074.jpg



View of the vegetation on the upstream of the channel. Summer 2018

Rating **	A	Issue No.	62	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_62			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	63	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_63			

Action/Comments

Inspector Comments: No erosion or bank caving is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Jack Tone Rd / Up (cont)

Rating **	A	Issue No.	64	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_64			

Action/Comments

Inspector Comments: Existing riprap protection has minimal vegetation but appears properly maintained.

Photo 1 of 1 : CH_2018_NA0017_44_64_20180530_00034.jpg



View of existing riprap on the upstream of the channel.

Rating **	A	Issue No.	70	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_70			

Action/Comments

Inspector Comments: No trash or debris was found during the inspection.

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Jack Tone Rd / Down

Rating **	A	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_66			
Action/Comments				
Inspector Comments: Minimal vegetation was present in the channel but flow may not be impeded..				

Photo 1 of 1 : CH_2018_NA0017_44_66_20180703_00075.jpg



View of the channel looking downstream. Summer 2018

Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_67			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_68			
Action/Comments				
Inspector Comments: No erosion is present on the channel bank.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Jack Tone Rd / Down (cont)

Rating **	A	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		37.880726 °
Category	Rivers, Channels & Designated Flood			-121.146929 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_69			

Action/Comments

Inspector Comments: Existing riprap protection has minimal vegetation but appears properly maintained.

Photo 1 of 1 : CH_2018_NA0017_44_69_20180530_00037.jpg



View of the existing riprap on the channel bank looking downstream.

Check Point / View

Austin Rd / Up

Rating **	A	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_71			

Action/Comments

Inspector Comments: Minimal vegetation is present in the channel, but the flow is not impeded.

Photo 1 of 1 : CH_2018_NA0017_44_71_20180703_00072.jpg



View of vegetation on the upstream side of the channel. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View				
Austin Rd / Up (cont)				
Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_72			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

No Photos

Rating **	A	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_73			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

No Photos

Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_74			
Action/Comments				
Inspector Comments: No revetments are present at this location.				

No Photos

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Austin Rd / Up (cont)

Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_75			

Action/Comments

Inspector Comments: No trash or debris was found during the inspection.

No Photos

Check Point / View

Austin Rd / Down

Rating **	A	Issue No.	76	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_76			

Action/Comments

Inspector Comments: Minimal vegetation growth is found, but it does not appear to impede the flow of the channel.

Photo 1 of 1 : CH_2018_NA0017_44_76_20180703_00073.jpg



View of the vegetation on the downstream end of the channel. Summer 2018

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_77			

Action/Comments

Inspector Comments: No sediment was present during inspection.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Austin Rd / Down (cont)

Rating **	A	Issue No.	78	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_78			
Action/Comments				
Inspector Comments: No erosion or bank caving is present.				

No Photos

Rating **	A	Issue No.	79	GPS Lat/Long
Issue Type +	Ma	Location *		37.872720 °
Category	Rivers, Channels & Designated Flood			-121.183100 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_79			
Action/Comments				
Inspector Comments: Existing revetments are properly maintained.				

Photo 1 of 1 : CH_2018_NA0017_44_79_20180530_00041.jpg



View of the revetments on the downstream of the channel.

Rating **	A	Issue No.	80	GPS Lat/Long
Issue Type +	Ma	Location *		37.872482 °
Category	Rivers, Channels & Designated Flood			-121.182910 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_80			
Action/Comments				
Inspector Comments: No trash or debris was found during the inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Highway 99 / Up

Rating **	M	Issue No.	81	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_81			

Action/Comments

Inspector Comments: Vegetation growth may impede the flow of the channel.

Photo 1 of 2 : CH_2018_NA0017_44_81_20180625_00071.jpg



View of vegetation on the upstream of the channel. Summer 2018

Photo 2 of 2 : CH_2018_NA0017_44_81_20180530_00042.jpg



View of vegetation on the upstream of the channel. Summer 2017

Rating **	M	Issue No.	82	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_82			

Action/Comments

Inspector Comments: Non aquatic grasses are present at this location. Unable to inspect in 2018 due to vegetation growth.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Highway 99 / Up (cont)

Rating **	M	Issue No.	83	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_83			

Action/Comments

Inspector Comments: Erosion is present on the bank of the channel near the pipe outlet. Unable to inspect in 2018 due to vegetation growth.

Photo 1 of 2 : CH_2018_NA0017_44_83_20180530_00043.jpg



View of the erosion on the channel bank looking upstream. Summer 2017

Rating **	M	Issue No.	83 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_83			

Photo 2 of 2 : CH_2018_NA0017_44_83_20180530_00044.jpg



Updated picture of the erosion on the left bank of the channel looking upstream.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Highway 99 / Up (cont)

Rating **	A	Issue No.	84	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_84			
Action/Comments				
Inspector Comments: Existing revetments were properly maintained at this location. Unable to inspect in 2018 due to vegetation growth.				

Photo 1 of 1 : CH_2018_NA0017_44_84_20180530_00045.jpg



View of the existing revetments on the upstream end of the channel.

Rating **	A	Issue No.	85	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_85			
Action/Comments				
Inspector Comments: No trash was present during the inspection. Unable to inspect in 2018 due to vegetation growth.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Highway 99 / Down

Rating **	M	Issue No.	86	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_86			

Action/Comments

Inspector Comments: Vegetation may impede the flow of the channel.

Photo 1 of 2 : CH_2018_NA0017_44_86_20180625_00068.jpg



View of the vegetation on the downstream side of the channel. Summer 2018

Rating **	M	Issue No.	86 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2012_86			

Photo 2 of 2 : CH_2018_NA0017_44_86_20180625_00070.jpg



Another view of the vegetation on the downstream side of the channel. Summer 2018

Rating **	A	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2012_87			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Highway 99 / Down (cont)

Rating **	A	Issue No.	88	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2012_88			
Action/Comments				
Inspector Comments: No erosion is present.				

No Photos

Rating **	A	Issue No.	89	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2012_89			
Action/Comments				
Inspector Comments: Existing riprap was properly maintained at this location.				

Photo 1 of 1 : CH_2018_NA0017_44_89_20180625_00069.jpg



View of the existing revetments on the downstream of the channel.
Summer 2018

Rating **	A	Issue No.	90	GPS Lat/Long
Issue Type +	Ma	Location *		37.872077 °
Category	Rivers, Channels & Designated Flood			-121.219318 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2012_90			
Action/Comments				
Inspector Comments: No trash was present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View


El Dorado Rd. / Up

Rating **	M	Issue No.	120	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2014_120			

Action/Comments

Inspector Comments: Tree limbs have fallen into the channel that may impede the flow.

Photo 1 of 2 : CH_2018_NA0017_44_120_20180625_00065.jpg



View of the channel looking upstream. Summer 2018

Rating **	M	Issue No.	120 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2014_120			

Photo 2 of 2 : CH_2018_NA0017_44_120_20180625_00066.jpg



View of the debris in the water looking upstream. Summer 2018

Rating **	A	Issue No.	121	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2014_121			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

El Dorado Rd. / Up (cont)

Rating **	A	Issue No.	122	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2014_122			
Action/Comments				
Inspector Comments: No erosion is present.				

No Photos

Rating **	N	Issue No.	123	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2014_123			
Action/Comments				
Inspector Comments: There is no revetment at this location.				

No Photos

Rating **	A	Issue No.	124	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2014_124			
Action/Comments				
Inspector Comments: No trash or debris was found on the channel.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

El Dorado Rd. / Down

Rating **	A	Issue No.	125	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_44_c_2014_125			

Action/Comments

Inspector Comments: Tree branches may fall into the channel, but the flow is not impeded.

Photo 1 of 1 : CH_2018_NA0017_44_125_20180625_00067.jpg



View of the channel downstream during 2018 inspection.

Rating **	A	Issue No.	126	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_44_c_2014_126			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	127	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_44_c_2014_127			

Action/Comments

Inspector Comments: No erosion is present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek	21.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

El Dorado Rd. / Down (cont)

Rating **	N	Issue No.	128	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Revetments			
DWR ID	DWR_NA0017_44_c_2014_128			

Action/Comments

Inspector Comments: There is no revetment at this location.

No Photos

Rating **	A	Issue No.	129	GPS Lat/Long
Issue Type +	Ma	Location *		37.894480 °
Category	Rivers, Channels & Designated Flood			-121.275977 °
Item	Encroachments			
DWR ID	DWR_NA0017_44_c_2014_129			

Action/Comments

Inspector Comments: No trash or debris was found on the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2018 Channel Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Channel
South Littlejohn Creek North Branch

Channel Rating	A
Date of Inspection	6/22/2018 - 6/28/2018
DWR Inspector	Dave Torres
Accompanied By	Jim Caruso SJCFC&WCD

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Diversion / Down

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_6			

Action/Comments

Inspector Comments: Minimal vegetation in the channel should not impede the flow.

Rating **	A	Issue No.	6 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_6			

Photo 1 of 2 : CH_2018_NA0017_45_6_20180702_00038.jpg



View of the confluence looking downstream. Summer 2018

Photo 2 of 2 : CH_2018_NA0017_45_6_20180530_00001.jpg



View of the confluence looking downstream.

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_7			

Action/Comments

Inspector Comments: No sedimentation is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Diversion / Down (cont)

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_8			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location.				

No Photos

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_9			
Action/Comments				
Inspector Comments: No revetments exist at this location.				

No Photos

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		37.888860 °
Category	Rivers, Channels & Designated Flood			-121.130320 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_10			
Action/Comments				
Inspector Comments: No trash was found during inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Jack Tone Rd / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_11			

Action/Comments

Inspector Comments: Minimal vegetation in the channel should not impede the flow.

Photo 1 of 1 : CH_2018_NA0017_45_11_20180702_00035.jpg



View of the channel looking upstream during 2018 inspection.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_12			

Action/Comments

Inspector Comments: No sedimentation is present.

No Photos

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_13			

Action/Comments

Inspector Comments: No erosion or bank caving is present at this location.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Jack Tone Rd / Up (cont)

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_14			

Action/Comments

Inspector Comments: Existing riprap is properly maintained at this location.

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_15			

Action/Comments

Inspector Comments: No trash was found during the inspection.

No Photos

Check Point / View

Jack Tone Rd / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_16			

Action/Comments

Inspector Comments: Minimal vegetation in the channel should not impede the flow.

Photo 1 of 1 : CH_2018_NA0017_45_16_20180702_00036.jpg



View of the channel looking downstream. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Jack Tone Rd / Down (cont)

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_17			

Action/Comments

Inspector Comments: No sedimentation is present at this location.

No Photos

Rating **	M	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_18			

Action/Comments

Inspector Comments: Minor erosion or bank caving is present.

Photo 1 of 2 : CH_2018_NA0017_45_18_20180702_00037.jpg



View of bank erosion on the downstream of the channel. Summer 2018

Rating **	M	Issue No.	18 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_18			

Photo 2 of 2 : CH_2018_NA0017_45_18_20180530_00007.jpg



View of bank erosion on the downstream of the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Jack Tone Rd / Down (cont)

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_19			

Action/Comments

Inspector Comments: Existing revetments appeared to be properly maintained.

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		37.889520 °
Category	Rivers, Channels & Designated Flood			-121.146980 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_20			

Action/Comments

Inspector Comments: No trash or debris are present at this location.

No Photos

Check Point / View

Austin Rd / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_21			

Action/Comments

Inspector Comments: Minimal vegetation in the channel should not impede the flow.

Photo 1 of 3 : CH_2018_NA0017_45_21_20180702_00030.jpg



View upstream of the channel. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Austin Rd / Up (cont)

Rating **	A	Issue No.	21 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_21			

Action/Comments

Inspector Comments: Minimal vegetation in the channel should not impede the flow.

Photo 2 of 3 : CH_2018_NA0017_45_21_20180530_00010.jpg



View of the vegetation on the upstream of the channel. Summer 2017

Photo 3 of 3 : CH_2018_NA0017_45_21_20180530_00011.jpg



View of the vegetation on the channel looking upstream during 2016 inspection.

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_22			

Action/Comments

Inspector Comments: No sedimentation is present at this location.

No Photos

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View				
Austin Rd / Up (cont)				
Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056°
Category	Rivers, Channels & Designated Flood			-121.183664°
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_23			
Action/Comments				
Inspector Comments: No erosion present at this location.				

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_24			
Action/Comments				
Inspector Comments: LMA has placed revetments on both banks of the channel. Permit#19001. Existing revetments are properly maintained.				

Photo 1 of 1 : CH_2018_NA0017_45_24_20180702_00031.jpg



View of the revetments on the left bank of the channel. Summer 2018

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_25			
Action/Comments				
Inspector Comments: No trash or debris was found during inspection.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Austin Rd / Down

Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_26			
Action/Comments				
Inspector Comments: Willows and other woody vegetation should be trimmed back before it impedes channel capacity.				

Photo 1 of 1 : CH_2018_NA0017_45_26_20180702_00032.jpg



View of the channel downstream. Summer 2018

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_27			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	M	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_28			
Action/Comments				
Inspector Comments: Erosion was found on the right bank of the channel.				

Photo 1 of 2 : CH_2018_NA0017_45_28_20180702_00033.jpg



View of the erosion on the right bank of the channel. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Austin Rd / Down (cont)

Rating **	M	Issue No.	28 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_28			
Action/Comments				
Inspector Comments: Erosion was found on the right bank of the channel.				

Photo 2 of 2 : CH_2018_NA0017_45_28_20180530_00014.jpg



View of the erosion on the right bank of the channel. Summer 2017

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_29			
Action/Comments				
Inspector Comments: LMA has placed riprap at this location. Permit #19001. Existing revetments are properly maintained.				

Photo 1 of 1 : CH_2018_NA0017_45_29_20180702_00034.jpg



View of the revetment on the right bank of the channel. Summer 2018

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		37.886056 °
Category	Rivers, Channels & Designated Flood			-121.183664 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_30			
Action/Comments				
Inspector Comments: No trash or debris was found during inspection.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Confluence at Airport Way / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_31			
Action/Comments				
Inspector Comments: Minimal scattered vegetation is unlikely to impede the flow of the channel.				

Photo 1 of 1 : CH_2018_NA0017_45_31_20180625_00022.jpg



View of the confluence looking upstream. Summer 2018

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_32			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_33			
Action/Comments				
Inspector Comments: No erosion is present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Confluence at Airport Way / Up (cont)

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_34			

Action/Comments

Inspector Comments: No revetments are present at this location.

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_35			

Action/Comments

Inspector Comments: No trash or debris is present.

No Photos

Check Point / View

Confluence at Airport Way / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2012_36			

Action/Comments

Inspector Comments: Minimal scattered vegetation is unlikely to impede the flow of the channel.

Photo 1 of 1 : CH_2018_NA0017_45_36_20180625_00023.jpg



View of the channel looking downstream during 2018 inspection.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Confluence at Airport Way / Down (cont)

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2012_37			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2012_38			
Action/Comments				
Inspector Comments: No erosion or bank caving is present at this location				

No Photos

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2012_39			
Action/Comments				
Inspector Comments: No revetments exist at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Confluence at Airport Way / Down (cont)

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		37.876513 °
Category	Rivers, Channels & Designated Flood			-121.236231 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2012_40			

Action/Comments

Inspector Comments: No trash or debris is present at this location.

No Photos

Check Point / View

Highway 99 / Up

Rating **	M	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2013_41			

Action/Comments

Inspector Comments: Dense and woody vegetation may impede the flow of the channel.

Photo 1 of 2 : CH_2018_NA0017_45_41_20180625_00026.jpg



View of the vegetation on the upstream side of the channel. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Highway 99 / Up (cont)

Rating **	M	Issue No.	41 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c_2013_41			
Action/Comments				
Inspector Comments: Dense and woody vegetation may impede the flow of the channel.				

Photo 2 of 2 : CH_2018_NA0017_45_41_20180625_00029.jpg



Another view of the vegetation on the upstream side of the channel.
Summer 2018

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2013_42			
Action/Comments				
Inspector Comments: No sedimentation is present.				

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2013_43			
Action/Comments				
Inspector Comments: Existing revetments were properly maintained.				

Photo 1 of 1 : CH_2018_NA0017_45_43_20180530_00019.jpg



View of the existing revetment looking upstream.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Highway 99 / Up (cont)

Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2013_44			
Action/Comments				
Inspector Comments: No trash was found at this location.				

No Photos

Check Point / View

Highway 99 / Down

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0017_45_c _ 2013_45			
Action/Comments				
Inspector Comments: Vegetation in the channel should not impede the flow.				

Photo 1 of 1 : CH_2018_NA0017_45_45_20180625_00025.jpg



View of the channel looking downstream. Summer 2018

Rating **	A	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0017_45_c_2013_46			
Action/Comments				
Inspector Comments: No sedimentation is present at this location.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

San Joaquin County Flood Control and Water Conservation District

Channel	Channel Length	Inspection Start/End	Inspector
South Littlejohn Creek North Branch	7.00	06/22/2018 06/28/2018	Dave Torres

Check Point / View

Highway 99 / Down (cont)

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0017_45_c_2013_47			
Action/Comments				
Inspector Comments: No erosion was present during the inspection.				

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Revetments			
DWR ID	DWR_NA0017_45_c_2013_48			
Action/Comments				
Inspector Comments: Existing revetments were properly maintained.				

Photo 1 of 1 : CH_2018_NA0017_45_48_20180625_00024.jpg



View of the revetments on both banks looking at the downstream side of the channel. Summer 2018

Rating **	A	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		37.875127 °
Category	Rivers, Channels & Designated Flood			-121.219201 °
Item	Encroachments			
DWR ID	DWR_NA0017_45_c_2013_49			
Action/Comments				
Inspector Comments: No trash was present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement